

Frequently Asked Questions

Q. Is there a point of contact for information on the GFE DOMSAT service?

A. The DOMSAT point of contact at Americom Government Services is Larry Wheeler. Americom can be reached at (609)987-4235. Minimum performance requirements for the DOMSAT service are as follows: Bit Error Rate (BER) of 10^{-8} ; circuit delay of 600 milliseconds; and data availability of 99.5%.

Q. Will there be an electronics shelter to house the antenna control equipment at the MSG HRIT receive antenna site?

A. There is not a GFE shelter provided at the MSG HRIT receive antenna pad location.

Q. What is the demarcation point for connecting the HBS modem to the DOMSAT antenna?

A. The demarcation point for the DOMSAT antenna will be in the operations building so no cabling will be required.

Q. How can Government forms be obtained electronically for submitting proposals to this solicitation?

A. Standard Forms are available for download at the following URL:
<http://contacts.gsa.gov/webforms.nsf>.